

Reliable Home Inspection

Radon Sampling Report

Test Address: 123 Spring Street Our Town, U.S.A.
Test Location: Basement
Test Start Time: March 3, 2009 @ 3:00 pm
Test End Time: March 5, 2009 @ 3:30 pm
Monitor #1: 3.1 pCi/L
Monitor #2: 3.5 pCi/L

Test Results: 3.3 pCi/L

The Environmental Protection Agency recommends mitigation action be taken for test results of 4.0 pCi/L or higher. Please visit www.epa.gov/radon for more information.

The residence described above has been short term protocol tested (48 hours) for the presence of radon using 2 Pro Series 3 Radon gas detectors. The test and analysis have been performed in accordance with the Environmental Solutions Association (ESA) radon testing protocol. The Test Results represents the average radon concentration at the time the sampling was conducted and at the specific location within the building. Please note that radon concentrations will vary from day to day and from season to season. No tampering was observed during the radon testing period.